

**ENGINEER EQUIPMENT MECHANIC NCO
Concept Card Report**

ANNEX I - EXAMS

LESSON ID: NCOM - A02X(W)

HOURS: 2.00

TYPE: Exam

CATEGORY: Training

TITLE: Maintenance Management

PHASE:

GROUP

METHOD	HOURS	S:I RATIO
X(W)	2.00	25 : 1

MEDIA: TSTBK

TERMINAL LEARNING OBJECTIVE(S)

- 1 . Provided engineer equipment and references, complete engineer equipment records and forms, to support mission requirements. (1341-ADMN-2003)
- 2 . Given a requirement, data, and the references, review service request and parts requirement, Per the references. (1341-ADMN-2004)
- 3 . Provided an item of engineer equipment, and the references, complete commodity manager's modification control record, to record equipment modifications. (1341-ADMN-2005)
- 4 . Given a requirement and the references, maintain pre-expended bins (PEB), to ensure bins are stocked and maintained for timely maintenance. (1341-ADMN-2007)
- 5 . Provide a service request, parts requirement, repair parts, and the references, maintain layettes, to ensure repair parts are kept in the appropriate layettes bin. (1341-ADMN-2008)



ENGINEER EQUIPMENT MECHANIC NCO

Concept Card Report

ANNEX I - EXAMS

LESSON ID: NCOM - A02X(W)

HOURS: 2.00

TYPE: Exam

CATEGORY: Training

TITLE: Maintenance Management

PHASE:

GROUP

ENABLING LEARNING OBJECTIVE(S)

1. Without the aid of references, complete the NAVMC 10560 (LTI) per the TM-4700-15/1_. (1341-ADMN-2003a)
2. With the aid of references, create a service request per the GPN 3-12 and GPN 1-13. (1341-ADMN-2004a)
3. With the aid of references, close a service request per the GPN 3-12 and GPN 1-13. (1341-ADMN-2004b)
4. Without the aid of reference, identify the purpose of a parts request, per the GPN 1-11, GPN 3-11, GPN 2-12, GPN 10-12, GPN 1-13, GPN 3-13 and MCO P4790.2_. (1341-ADMN-2008a)
5. Without the aid of references, complete the SF 368 (PQDR) per the TM-4700-15/1_. (1341-ADMN-2003b)
6. Provided a computer, internet access, T/E and references, validate modification program per the GPN 4-12 and MCO P4790.2_. (1341-ADMN-2005a)
7. Without the aid of reference, identify the requirements for the demand-supported items authorization letter, per the MCO P4400.150_. (1341-ADMN-2007a)
8. Without the aid of reference, identify procedures for inventory of demand-supported Items, per the MCO 4400.150_, GPN 1-11, GPN 3-12 and MCO P4790.2_. (1341-ADMN-2007b)
9. Without the aid of references, identify Sub-inventory Locator procedures, per the MCO P4790.2_, GPN



Date: 20140506

ENGINEER EQUIPMENT MECHANIC NCO

Concept Card Report

ANNEX I - EXAMS

LESSON ID: NCOM - A02X(W)

HOURS: 2.00

TYPE: Exam

CATEGORY: Training

TITLE: Maintenance Management

PHASE:

GROUP

1-11, GPN 3-11, GPN 2-12, GPN 10-12, GPN 1-13, GPN 3-13 and TM 4400-150_
(1341-ADMN-2008b)

NOTE(S):

REFERENCE - TITLE

PUBLICATION ID

CHAPTER/PAGE

Consumer Level Supply Policy Manual

MCO P4400.150_

Current GCSS-MC Procedural Notices (GPN)

Ground Equipment Record Procedures

TM 4700-15/1_

MIMMS Field Procedures Manual

MCO P4790.2_



**ENGINEER EQUIPMENT MECHANIC NCO
Concept Card Report**

ANNEX A - MAINTENANCE MANAGEMENT

LESSON ID: NCOM - A02

HOURS: 20.50

TYPE: Task Oriented

CATEGORY: Training

TITLE: Maintenance Management

PHASE:

GROUP

METHOD	HOURS	S:I RATIO
D	0.50	25 : 1
L	10.00	25 : 1
PA	9.00	25 : 1
Q	1.00	25 : 1

MEDIA: CPU, DB, HO, PPT

TERMINAL LEARNING OBJECTIVE(S)

- 1 . Provided engineer equipment and references, complete engineer equipment records and forms, to support mission requirements. (1341-ADMN-2003)
- 2 . Given a requirement, data, and the references, review service request and parts requirement, Per the references. (1341-ADMN-2004)
- 3 . Provided an item of engineer equipment, and the references, complete commodity manager's modification control record, to record equipment modifications. (1341-ADMN-2005)
- 4 . Given a requirement and the references, maintain pre-expended bins (PEB), to ensure bins are stocked and maintained for timely maintenance. (1341-ADMN-2007)



ENGINEER EQUIPMENT MECHANIC NCO
Concept Card Report

ANNEX A - MAINTENANCE MANAGEMENT

LESSON ID: NCOM - A02

HOURS: 20.50

TYPE: Task Oriented

CATEGORY: Training

TITLE: Maintenance Management

PHASE:

GROUP

- 5 . Provide a service request, parts requirement, repair parts, and the references, maintain layettes, to ensure repair parts are kept in the appropriate layettes bin. (1341-ADMN-2008)

ENABLING LEARNING OBJECTIVE(S)

- 1 . Without the aid of references, complete the NAVMC 10560 (LTI) per the TM-4700-15/1_. (1341-ADMN-2003a)
- 2 . With the aid of references, create a service request per the GPN 3-12 and GPN 1-13. (1341-ADMN-2004a)
- 3 . With the aid of references, close a service request per the GPN 3-12 and GPN 1-13. (1341-ADMN-2004b)
- 4 . Without the aid of reference, identify the purpose of a parts request, per the GPN 1-11, GPN 3-11, GPN 2-12, GPN 10-12, GPN 1-13, GPN 3-13 and MCO P4790.2_. (1341-ADMN-2008a)
- 5 . Without the aid of references, complete the SF 368 (PQDR) per the TM-4700-15/1_. (1341-ADMN-2003b)
- 6 . Provided a computer, internet access, T/E and references, validate modification program per the GPN 4-12 and MCO P4790.2_. (1341-ADMN-2005a)
- 7 . Without the aid of reference, identify the requirements for the demand-supported items authorization letter, per the MCO P4400.150_. (1341-ADMN-2007a)



ENGINEER EQUIPMENT MECHANIC NCO
Concept Card Report

ANNEX A - MAINTENANCE MANAGEMENT

LESSON ID: NCOM - A02

HOURS: 20.50

TYPE: Task Oriented

CATEGORY: Training

TITLE: Maintenance Management

PHASE:

GROUP

- 8. Without the aid of reference, identify procedures for inventory of demand-supported Items, per the MCO 4400.150_, GPN 1-11, GPN 3-12 and MCO P4790.2_. (1341-ADMN-2007b)
- 9. Without the aid of references, identify Sub-inventory Locator procedures, per the MCO P4790.2_, GPN 1-11, GPN 3-11, GPN 2-12, GPN 10-12, GPN 1-13, GPN 3-13 and TM 4400-150_. (1341-ADMN-2008b)

NOTE(S):

<u>REFERENCE - TITLE</u>	<u>PUBLICATION ID</u>	<u>CHAPTER/PAGE</u>
Consumer Level Supply Policy Manual	MCO P4400.150_	
Current GCSS-MC Procedural Notices (GPN)		
Ground Equipment Record Procedures	TM 4700-15/1_	
MIMMS Field Procedures Manual	MCO P4790.2_	

